

TECHNICAL BULLETIN

SUBJECT: Aqualung America Regulator service kit update

PRODUCTS AFFECTED: RG911115 / RG911116 / RG911117 / 900023 / 900010 / 900009 / 900016

Dear Aqualung Dealer, In an effort to align with a global offering, Aqualung America is making an adjustment to the service kits that will reflect the service kits offered from Aqualung International. Please be aware when ordering service kits that our previous kits are no longer available and have been replaced with new kits that are more specific to certain regulator models.

First Stage Kits

RG911115 for Cousteau/Spectrum/Titan/Conshelf
is replaced with

RA121114 for Cousteau/Spectrum
RA121122 for Old model Titan/Conshelf

RG911116 for Calypso/Aquarius/Mirage
is replaced with

RA121111 for Calypso(<2003)/Aquarius/Mirage
RA121124 for Calypso(2004>)

RG911117 for Legend/Mikron/Core/Titan/Kronos/Titan LX
is replaced with

RA121126 for Over-Balanced Legends
RA121125 for Balanced Diaphragms/Core/Mikron/Titan/Titan LX (not Kronos)
RA121119 for Kronos

Second Stage Kits

900023 for Balanced 2nd stages/Legend/Core/Titan LX/Mikron/Kronos
is replaced with

RA121128 for Balanced 2nd stage/Legend/Core/Mikron/Titan LX (not Kronos)
RA121121 for Kronos

900010 for Titan/Calypso/ABS/LPO/Glacia(old model)
is replaced with

RA121127 for Unbalanced 2nd stage/Titan/Calypso
RA121123 for ABS/LPO

900009 for Impulse/Cryo/XR2
is replaced with

RA121116 for Impulse/Cryo/XR2

900016 for Mistral Complete
is replaced with

RA121118 for Mistral Complete

**Should you have any questions regarding this issue,
please contact our customer service department at:
(877) 253-DIVE**