

## COLD WATER DIVING KIT (CWD)

For use in cold water diving (below 47 F) we recommend that a Cold Water Diving Kit (CWD) be installed. The assembly of this kit must be performed by a Mares authorized service center.

### WARNING !

DIVING IN COLD WATER (BELOW 47 F) WITHOUT PROPER TRAINING CAN CAUSE SERIOUS INJURY. BEFORE DIVING IN COLD WATER, SPECIAL TRAINING FROM A CERTIFIED INSTRUCTOR SHOULD BE OBTAINED.

ANY SCUBA DIVING REGULATOR, EVEN THOSE EQUIPPED WITH A CWD KIT CAN UNDERGO "FREEZE-UP" PHENOMENA. "FREEZE-UP" OF A REGULATOR IS DETRIMENTAL TO THE EFFICIENCY OF A REGULATOR AND CAN CAUSE THEM TO FAIL, THUS INTERRUPTING AIR DELIVERY TO THE DIVER. THIS MAY CAUSE SERIOUS INJURY OR DEATH. TO MINIMIZE SUCH RISKS, DIVERS SHOULD BE PROPERLY TRAINED TO PREVENT OR BE ABLE TO COPE WITH A REGULATOR AFFECTED BY "FREEZE-UP" PHENOMENA.




Fig. 1